










GP037-0002,1



ACCESSORY LIST

P07  1x	B.A.M	A28  1x	3,5x50	A16  1x	DbØ8
--	--------------	--	---------------	--	-------------

1 step



2^{step}

