



GP041-0032,3




A


x2

B

x2


C

x2

D

x3


a x1



b x1




c x4



M3.5x50

d x12










M4x35

e x4




f x6




01**02**

| | | | |
|-------|----|---|-----|
| a | x1 | b | x1 |
| screw | | | nut |


| | |
|-----|---------|
| c | x4 |
| nut | hex nut |

03


| | |
|---------|---------|
| d | x4 |
| nut | hex nut |
| M3.5x50 | |

04

| | |
|-------|---------|
| e | x6 |
| nut | hex nut |
| M4x35 | |

05

| | |
|-------|---------|
| e | x6 |
| nut | hex nut |
| M4x35 | |

06

| | |
|--------|--------|
| f | x10 |
| circle | circle |