






GP042-0005,1



























The necessary tools (not included)


ACCESSORY LIST

A02  20x	A01  20x	A03  20x	A12  4x	A13  4x
A10 <small>3,5x18</small>  32x	A09 <small>4x50</small>  11x	A64  2x	A14 <small>M4x22</small>  4x	A67  1x
A29 <small>3,5x30</small>  4x	A08  3x	A04  A 20x	A16  A 11x	B49  2x
B50  2x	A28  20x			




GENERAL VIEW






1




2




3








4






5




6




7





8



A09





9



B50


A10

10



A16

965 mm



Ø7 mm

A08

A09

A16

