





GP042-0029,1





















The necessary tools (not included)


ACCESSORY LIST

A02  20x	A01  20x	A03  20x	A09 4x50  16x	A10 3,5x18  16x
A08  2x	A13  4x	A12  4x	A28  25x	A34  2x
A04  A 16x D 4x	A16  A 6x D 10x	A17  1x		


GENERAL VIEW




1







2




3









6




7




8


8



9



10



11

