






GP042-0034,1





















This unit should be assembled by two persons.
The necessary tools (not included)


ACCESSORY LIST

A02  20x	A01  20x	A03  18x	A09 4x50  15x	A12  4x
A13  4x	A08 Ø8  2x	A10 3,5x18  16x	A28  16x	A16  9x
A04  A 20x				




GENERAL VIEW






1



2




3






6




4




5





6




7





8





10



Ø7 mm

A08

A09

A16

