






GP042-0104,1













The necessary tools (not included)


ACCESSORY LIST

A09  4x50 70x	A04  A 28x D 40x	A07  2x	A10  3,5x18 YHB 2x	A08  Ø8 2x



GENERAL VIEW





1



2






3




6


4




5




7




PART-1



PART-2



PART-3



PART-4

