






GP042-0146,1















The necessary tools (not included)

ACCESSORY LIST


| | | | | |
|---|--|---|---|--|
| A01 | A02 | A16 | A04 | A24 128 mm |
|  4x |  4x |  A 24x |  A 4x |  3x |
| A14 M4x22  6x | A28  20x | A10 3,5x18  41x | A12  4x | A13  4x |
| A09 4x50  25x | A39 10cm  4x | A40 25 cm  1x | A07  1x | A08 Ø8  1x |

GENERAL VIEW









2



3



4



5

