





GP042-0169,1








The necessary tools (not included)


ACCESSORY LIST

A02 16x	A01 16x	A03 16x	A12 6x	A13 6x
A28 20x	A04 A 16x	A10 32x <small>3,5x18</small>	A41 4x	D41 4x <small>5x70</small>
D69 4x <small>Ø8</small>	G18 1x <small>1800 mm</small>			


GENERAL VIEW




1









2





3











6



A41  Ø7 mm	D69 
 D41	 A10

7

