






GP042-0169,3






















The necessary tools (not included)


ACCESSORY LIST

A02  16x	A01  16x	A03  16x	A12  6x	A13  6x
A28  20x	A04  A 16x	A10 <small>3,5x18</small>  32x	A41  4x	D41 <small>5x70</small>  4x
D69 <small>Ø8</small>  4x	G18  <small>1800 mm</small> 1x			


GENERAL VIEW




1









2





3







6



A41	 Ø7 mm	 D69
 D41	 A10	

7

