






GP042-0170,2




















The necessary tools (not included)


ACCESSORY LIST

| | | | | |
|--|---|--|--|--|
| A16  A 12x | A28  15x | A41  4x | D69 $\varnothing 8$ RKT  4x | A09 4x50  12x |
| A10 3,5x18  24x | A12  4x | A13  4x | D41 5x70 YHB  4x | G15 LED  1340 mm 1x |


GENERAL VIEW



1




2




5



3






4





5




6



7




A41




Ø7 mm


D69



D41



A10



8

