






GP042-0170,3




















The necessary tools (not included)


ACCESSORY LIST

A16  A 12x	A28  15x	A41  4x	D69 $\varnothing 8$ RKT  4x	A09 4x50  12x
A10 3,5x18  24x	A12  4x	A13  4x	D41 5x70 YHB  4x	G15 LED  1340 mm 1x


GENERAL VIEW




1




2





3






4





5




6



7




A41




Ø7 mm


D69



D41



A10



8

