






**GP042-0196,3**

















The necessary tools (not included)




## ACCESSORY LIST

<b>A02</b>  <b>8x</b>	<b>A01</b>  <b>8x</b>	<b>B34</b>  <b>1x</b>	<b>B20</b> M6x10  <b>16x</b>	<b>B36</b>  <b>10x</b>
			<b>A10</b> 3,5x18  <b>10x</b>	<b>A04</b>  <b>A 8x</b>


## GENERAL VIEW




1






2






3




4



5



6



7

