






GP042-0217,1























The necessary tools (not included)


ACCESSORY LIST

A01  40x	A02  40x	A03  40x	A04  A 16x D 24x	A28  30x
A16  A 8x	A14 M4x22  4x	A24 128 mm  2x	A12  4x	A13  4x
A10 3,5x18  16x	A09 4x50  8x	F43  810*510 1x		


GENERAL VIEW




1




5




6




7



8



9



10

