






GP042-0218,1
























The necessary tools (not included)


ACCESSORY LIST



A01  32x	A02  32x	A03  32x	A11  4x	A13  4x
A08  3x $\varnothing 8$	A09  3x 4×50	A10  38x $3,5 \times 18$	A28  32x	A04  8x 24x A D
F65  1x	A27  10x	A41  1x	A16  2x D	

GENERAL VIEW




1









3






4




5




6





7






8




9








10



11





13

