






GP042-0004,2























The necessary tools (not included)


ACCESSORY LIST

A09 4x50  79x	A10 3,5x18  47x	A02  12x	A08  7x	A07  7x
A12  10x	A13  10x	A28  60x	A16 A 48x D 24x 	A04 D 12x 
D72 SYH  6x	A01  12x	A20 3,5x25  18x		


GENERAL VIEW



1



2



08


12

14


04

6

3




4




7


5






6







7



8







8




9

9




10





11





12





13





14





17






18





20



21

