






**GP042-0005,3**



























The necessary tools (not included)


## ACCESSORY LIST

<b>A02</b>  <b>20x</b>	<b>A01</b>  <b>20x</b>	<b>A03</b>  <b>20x</b>	<b>A12</b>  <b>4x</b>	<b>A13</b>  <b>4x</b>
<b>A10</b> <small>3,5x18</small>  <b>32x</b>	<b>A09</b> <small>4x50</small>  <b>11x</b>	<b>A64</b>  <b>2x</b>	<b>A14</b> <small>M4x22</small>  <b>4x</b>	<b>A67</b>  <b>1x</b>
<b>A29</b> <small>3,5x30</small>  <b>4x</b>	<b>A08</b>  <b>3x</b>	<b>A04</b>  <b>A 20x</b>	<b>A16</b>  <b>A 11x</b>	<b>B49</b>  <b>2x</b>
<b>B50</b>  <b>2x</b>	<b>A28</b>  <b>20x</b>			




## GENERAL VIEW






1




2




3








4






5



6




7




7



8



A09




9




B50

A10

10



A16



Ø7 mm

A08

A09

A16

