






GP042-0007,1
























The necessary tools (not included)


ACCESSORY LIST

A02  24x	A01  24x	A03  24x	A09 4x50  4x	A10 3,5x18  41x
A08 Ø8  4x	A13  4x	A12  4x	A14 M4x22  4x	A28  32x
B61 12 cm  5x	A24 128 mm  2x	A04  A 24x	A16  D 4x	


GENERAL VIEW




1





2



3




4




7

5




6





8


7







8





9



10



10



Ø7 mm

A08

A09

A16

