













GP042-0030,1



















The necessary tools (not included)





ACCESSORY LIST

A01  10x	A02  10x	A28  15x	A09 4x50  43x	A10 3,5x18  16x
A13  4x	A11  4x	A04  A 10x	A16  A 43x	



GENERAL VIEW




1




2




3




4




5





6




7



8



9



10

