






GP042-0046,2





















The necessary tools (not included)


ACCESSORY LIST

A02  16x	A01  16x	A03  16x	A09 4x50  34x	A10 3,5x18  36x
A13  4x	A12  4x	A28  30x	A47 5 cm  5x	A16  A 26x D 8x
A04  A 16x				


GENERAL VIEW




1





2






3







5







6



7




8





9


9



10




11



10

12



13

