






GP042-0067,1

















The necessary tools (not included)


ACCESSORY LIST

A01  52x	A02  36x	A03  16x	A09  4x50 12x	A44  8x
A04  A 4x D 48x	A16  A 12x			





GENERAL VIEW






1






2






3






4






5



6



7



7

