






GP042-0071,1
















The necessary tools (not included)


ACCESSORY LIST

A01  26x	A02  26x	A03  30x	A04  A 12x D 14x	A27  4x
A10 3,5x18  8x				


GENERAL VIEW









1



2









3




6

4



5



7

6

