





GP042-0169,4




















The necessary tools (not included)


ACCESSORY LIST

A02  16x	A01  16x	A03  16x	A12  6x	A13  6x
A28  20x	A04  A 16x	A10 3,5x18  32x	A41  4x	D41 5x70  4x
D69 Ø8  4x	G18  1800 mm 1x			


GENERAL VIEW




1






2






3









5





6



A41  Ø7 mm	D69 
 D41	 A10

7

