






GP042-0191,1
















The necessary tools (not included)


ACCESSORY LIST

A01  15x	A02  15x	A03  10x	A35  4x	A04  A15x
A10  20x 3,5x18				


GENERAL VIEW




1




2



3



4



5

