






GP042-0204,1










The necessary tools (not included)


ACCESSORY LIST

A01 36x <small>M4x22</small>	A02 36x	A03 16x	A10 <small>3,5x18</small> 24x	A28 28x
A14 6x	A04 A 36x	A16 A 12x	A24 3x	A09 <small>4x50</small> 12x
				A78 3x


GENERAL VIEW






1




5






3



4






5






7


6



7






8







8

9



10



11

12

13

