






GP042-0207,1














The necessary tools (not included)


ACCESSORY LIST


 <p>A01 43x</p>	 <p>A02 43x</p>	 <p>A03 35x</p>	 <p>A04 A 43x</p>	 <p>A12 4x</p>
 <p>A13 4x</p>	 <p>A09 4x50 YHB 4x</p>	 <p>A14 M4x22 3x</p>	 <p>A98 3x</p>	 <p>A25 "H" 864 mm 1x</p>
 <p>A36 3x</p>	 <p>A97 4x</p>	 <p>A28 72x</p>	 <p>A10 3,5x18 YHB 36x</p>	 <p>A43 30 cm 1x</p>
 <p>A16 4x</p>				

GENERAL VIEW




1







3






4








6




7




8




9





10




11





12






13





14





15






16






17






18



19



20



21

