






GP042-0226,1











The necessary tools (not included)

ACCESSORY LIST


A01 	A02 	A03 	D53 17mm 246 mm 1x 	A28 19x
A24 128 mm 1x 	A04 	A10 3,5x18 4x 	A09 4x50 4x 	D09 M4x15 2x
A14 M4x22 2x 	A16 			

GENERAL VIEW







2




3




4




5




6




7




8



9



10



11

