














GP042-0226,3






















The necessary tools (not included)


ACCESSORY LIST

A01  17x	A02  17x	A03  8x	D53  17mm 246 mm 1x	A28  19x
A24  128 mm 1x	A04  A 17x	A10  3,5x18 4x	A09  4x50 4x	D09  M4x15 2x
A14  M4x22 2x	A16  A 4x			




GENERAL VIEW






1






2




3




4





5




6






7




8



9



10



11

